


CULVERT CONDITIONS ASSESSMENT FOR LA DADE KOTOPON MUNICIPAL ASSEMBLY



LEGEND

Drain Assessment

- Earth Drain
- Lined Drain
- Main Streets
- Railway Line
- Water Body
- Ladma Boundary
- Lekma Boundary
- Adjoining Boundaries